


G0750G VFD Control Wiring



Notes:

- 1 - To change motor rotation switch any 2 of the 3 wires.
- 2 - Pin 8 is used for jog wiring and is marked as #6 in the control panel wiring.
- 3 - Interconnect cable shields are grounded on the VFD enclosure end only. The other ends float.

TITLE	DESCRIPTION	FILENAME
VFD Control Wiring	Grizzly G0750G Lathe VFD Modification	VFD_SCHEMATIC.VSD
DRAWN BY	DATE	REVISED
Steve Nance	11/6/2021	11/18/2021
		PAGE
		1 OF 1